

FBM320

Pressure Sensor Process Analysis Report

www.sitrigroup.com



Product Analysis Report

This report is protected by copyright and may not be by way of trade or otherwise, be copied, reproduced, re-sold, lent, hired out in any form without express written permission from Shanghai Industrial μ Technology Research Institute (Hereinafter referred to as SITRI). SITRI always endeavors to provide accurate and reliable information to its customers. However, it is not possible to guarantee absolute accuracy of all information contained herein and SITRI can assume no liability for inadvertent errors in this report.

This report was prepared for our Clients' private study, analysis or research and for no other purpose. The information contained in this report may describe technical innovations, which are the subject of patents held by third parties. The disclosure by SITRI of any such information is in no form whatsoever an inducement to infringe any patent. SITRI assumes no liability for patent infringement arising from the use of the information contained in this report.

Weibo



Wechat



To Know



- Device Summary.....3
 - Basic Device Summary Table
- Package and Die Information.....4
 - Package Information
 - ASIC Die Photo
 - Sensor Die IR Photo with Cavity Dimensions
 - Sensor Die Information
- Pressure Sensor Cross Section 4 Analysis.....13
 - Cross Section4 Analysis after Stained with Die Thickness
 - Cross Section4 Analysis after Stained with Cavity Length
 - Cross Section4 Analysis after Stained with Cavity to Edge Measurements
 - Cross Section4 Analysis after Stained with Contact Dimensions
 - Cross Section4 Analysis after Stained with Piezoresistive P+/P- Dimensions
- Pressure Sensor Cross Section 3 Analysis.....22
 - Cross Section3 Analysis without Stained with Die Thickness
 - Cross Section3 Analysis without Stained with Cavity Width
 - Cross Section3 Analysis without Stained with Cavity to Edge Measurement
 - Cross Section3 Analysis without Stained with Metal Line Dimensions

- Cross Section3 Analysis without Stained with Contact Dimensions
- Cross Section3 Analysis without Stained with Cavity Dimensions
- Cross Section3 Analysis without Stained with Surface Film Dimensions
- Pressure Sensor Cross Section 2 Analysis.....36
 - Cross Section2 Analysis after Stained with Center P+ Dimensions
 - Cross Section2 Analysis after Stained with Piezoresistive P+ Dimensions
 - Cross Section2 Analysis after Stained with P- Dimensions, P- Area for Test
- Pressure Sensor Cross Section 1 Analysis.....44
 - Cross Section1 Analysis after Stained with Center P+ Dimensions
 - Cross Section1 Analysis after Stained with Piezoresistive P+ Dimensions
- Pressure Sensor EDS Analysis.....53
 - EDS Analysis of Passivation Layer
 - EDS Analysis of Surface Film above Cavity
 - EDS Analysis of Metal
 - EDS Analysis of Cavity Area
- Major Findings.....64
 - Points