



Leshi Max2 LeX820

www.sitrigroup.com

Weibo



Wechat



Teardown Analysis Report

To Know



Table Of Contents

Teardown Analysis

Product Overview	Page 2
Packagings	Page 5
Exterior Features	Page 9
Major Components	Page 12
Teardown Sequence	Page 15
Switch	Page 18
Connector	Page 19
Electroacoustic	Page 21
Non-electronics	Page 23
Antenna	Page 26

Subsystem Analysis

Battery	Page 29
Rear Camera	Page 31
Front Camera	Page 35
TP Information	Page 39

Main Electronics Analysis

Non-electronics of Shields	Page 42
Shields Analysis	Page 44
PCB Board Analysis	Page 46
Connector Analysis	Page 51
Min Space Features	Page 56
Underfill Features	Page 58
IC Package Type Analysis	Page 59

www.sitrigroup.com

Weibo



Wechat



Leshi Max2 LeX820 Block Analysis Report

Table Of Contents

IC Identification	Page 64
Sensor IC Overview	Page 69
Main Board Cross-Section	Page 82
Function Block	Page 83
FPC Analysis	Page 86

Cost Analysis

Substrates	Page 89
IC Components	Page 90
Modular Components	Page 92
Discrete Components	Page 93
Connector Components	Page 95
Non-Electronic Cost Estimate	Page 96
Electronic Assembly Metrics	Page 97
Electronic Costs Breakdown	Page 101
Vendor IC Cost Distribution	Page 102
Cost Summary	Page 103
Final Ass'y Labor & Test Cost	Page 104

Major Findings Analysis

Product Findings	Page 105
Sensor Findings	Page 106
Cost Findings	Page 107

