


Samsung Galaxy S4 I9505

www.sitrigroup.com

Weibo



Wechat



Teardown Analysis Report

Table Of Contents

Teardown Analysis

Product Overview	Page 2
Teardown	Page 6
IC Analysis	Page 22
System Analysis	Page 33
Major Findings	Page 35

Sensor Analysis

Sensor Overview	Page 36
Accelerometer & Gyroscope Sensor	Page 37
Pressure Sensor	Page 42
Electronic Compass Sensor	Page 47
Humidity Sensor	Page 51
Gesture Sensor	Page 54
Ambient Light Sensor	Page 57
Image Sensor	Page 61
MEMS Microphone	Page 63
Hall Effect Sensor	Page 67
Major Findings	Page 70

Cost Analysis

Substrates	Page 68
IC Components	Page 69
Modular Components	Page 73
Discrete Components	Page 74
Connector Components	Page 76
Non-Electronic Cost Estimate	Page 77
Cost Summary	Page 78
Major Findings	Page 82

www.sitrigroup.com

Weibo



Wechat

