




Codoon HB-B01

www.sitrigroup.com

Weibo



Wechat



Teardown Analysis Report



Codoon HB-B01 Product Analysis Report

Table Of Contents

Teardown Analysis

Product Overview	Page 2
Teardown	Page 7
IC Analysis	Page 14
Major Findings	Page 15

Sensor Analysis

Sensor Overview	Page 16
Accelerometer Sensor	Page 17
Major Findings	Page 21

Cost Analysis

Substrates	Page 22
IC Components	Page 23
Modular Components	Page 27
Discrete Components	Page 28
Connector Components	Page 30
Non-Electronic Cost Estimate	Page 31
Cost Summary	Page 32
Major Findings	Page 36

www.sitrigroup.com

Weibo



Wechat

